

**Photo 5**

NDH. Native forest understorey at Dome Hill showing the recently disturbed patches of open ground where erosion can begin.



**Photo 6**

View north across the Manhurangi River left branch to the native forest at Dome Hill above the clear felled pine (foreground) which has been left to develop a substantial growth of weeds including wild ginger



**Photo 7**

NMH. Native forest understorey at Moir's Hill showing the dense leaf litter over very tightly packed fine fibrous roots. This is old undisturbed forest.



**Photo 8**

View of the native forest at Moir's Hill from the adjacent recently felled pine forest. The size of the trees indicates that this forest has not been disturbed for some time.





**Photo 9**

NCBR. Native forest understorey at Cowan Bay Road. This is heavy leaf litter beneath Kauri and Rimu regrowth and is essentially undisturbed in recent times.



**Photo 10**

View north across the native forest at Cowan Bay Road. The size of the trees indicates that this forest has not been disturbed for some time.





**Photo 11.**

EDH1. Exotic pine forest at Dome Hill showing the undisturbed understorey and leaf litter.



**Photo 12**

EDH2. Exotic pine forest at Dome Hill showing the disturbed and partially eroded and exposed subsoil.

